



# Jazz UltraTab C1059-HL Battery Replacement

This guide will give the necessary steps for replacing the battery.


Written By: Austen Shields



## INTRODUCTION



This guide will guide the user to effectively remove and replace the battery. This replacement will take 20-30 minutes. However, if the guide is followed to the letter, the task will be accomplished with minimal damage to the device.

## Step 1 — Battery



- remove the screws at the four corners of the device.

## Step 2




- Use a prying tool to pry the back panel from the tablet chassis. Pry the panel at different locations around the device to separate clips.

### Step 3



- Use a soldering iron to remove power cables from battery. The power cable is shown at the corner of the battery in the picture.

### Step 4



- Use a tool to carefully pry battery away from chassis. The battery is attached by an adhesive. Slowly pry battery on the side away from the motherboard.



## Step 5



- You have successfully removed the battery. Put new battery in the same location. Solder the supply wires. Reapply tape in original location.

---

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-19 07:10:38 PM.